

Notice



- ☐ CORRECTION
 ☒ PRODUCTION CHANGE
☐ SERVICE FLASH
 ☐ ADD INFORMATION

FILE NO.

REVISION 0

Please add this notice to the Service Manual listed below.

Category: **COLOR TELEVISION** Date: **SEPTEMBER / 23 / 2009**
 Model: **DP46848** Effective from : Chassis No. **P46848-07**
 Destination: **U.S.A. / CANADA** REF : **No. SM780153-07**

NOTE: Match the Chassis No. on the unit's back cover with the Chassis No. in the Service Manual. **If the Service Manual Chassis No. does not match the unit's**, additional Service Literature is required. This chassis is similar to Chassis No. P46848-00. Only the **difference** Service Information is given in this manual. For detailed Service Information, refer to the **Original** Service Manual and **Notices** for Chassis No. P46848-00 used in Model DP46848 (SM7800153).

SERVICING SHOULD BE PERFORMED BY ONLY TRAINED AND QUALIFIED SERVICE PERSONNEL.

1. IN THE SERVICE ADJUSTMENTS

PAGE 4 ON-SCREEN SERVICE MENU

Item No. **088 OP2 Data** should be changed from **33h** to **34h** in the table and in Note 2.

2. IN THE CHASSIS ELECTRICAL PARTS LIST MISCELLANEOUS

The reason for change.

- A : Misprint B : Quality Reliability C : Standardization
 D : Design E : Add as a possible sub F : Schematic location change
 G : Purchasing Request

Page & Section	Schematic Location		Part No.	Description	Q'ty	Interchange-ability	Reason
Page 25, Chassis Electrical Parts List	▲ EL901	Old	1AV4T40B97900	LCD(T460HW02 V1)	1	NO	D
		New	1AV4T40B98400	LCD(LK460D3LA12)	1	NO	
	U901	Old	1AV4U20C32500	UNIT,POWER	1	NO	D
		New	1AV4U20C33701	UNIT,POWER	1	NO	
	WK5LV-PN	Old	1AA4W30B53000	CORD 42INCH,40P-51P(LVDS)	1	NO	D
		New	1AA4W30B54200	CORD 40P-40P(LVDS)	1	NO	

For parts or service contact:

Sanyo Manufacturing Corporation
P.O. Box 2000
3333 Sanyo Road
Forrest City, Arkansas 72335-2000

September 2009 SMC

Published in Mexico

DP46848, N6EFF, PRODUCT CODE 113014204

REFERENCE No. SM780153-07